

Engineering Research Complex

Date/Number: **03Sept09**

Weather: **sunny/low 90's/dry**

Observations:

The following are observations from walking the site on Thursday, September 3, 2009.

- | | | |
|------------|--|----------------|
| 1. Bldg. A | Exterior window installation in progress. | (Photo 1 & 2) |
| 2. Bldg. B | Split face limestone masonry installation in progress. | (Photo 3&4) |
| 3. Bldg. B | Piers drilled for Generator/Dock area. | (Photo 5) |
| 4. Bldg. B | Rooftop AHU units installed and ductwork begun. | (Photo 6) |
| 5. Site | Site work along Yates continues. | (Photo 7 &8) |
| 6. Site | Duct bank installation along College Street in progress. | (Photo 9 & 10) |

END OF REPORT





Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6

UTA ERB Field Report – 03Sept09



Photo 7



Photo 8



Photo 9



Photo 10



UTA ERB Field Report 03Sept09

OFPC Project Number 301-258b